



photo 1: The abandoned pipe riser remains at the former tank battery site.
Lat/Long:39.98913,-104.63951



photo 2: Facing east along the access road to the location.



photo 3: Facing east near the location. The noxious weeds were mowed since the previous inspection. The location is northeast of this area and noxious weeds were not mowed at the location.



photo 4: A plastic pipe was found at the location. The noxious weeds were not mowed in this area.