

**Reference Area Photographs**

**Inspection Conducted on August 08, 2017**

**Chevron  
Environmental Management Company**

**Wilson Creek  
Terraced Area  
Location ID #443091  
REM #9622**

## Wilson Creek Terraced Area



View of the terraced area



View of the terraced area

Terrace #1 to the left; terrace #7 to the right, at the bottom of the valley

## Wilson Creek Terraced Area



View of the Terrace #1, excavated, sampled and back filled.  
Currently leveling and adding top soil.



Terraces #5 and #6 to the left.  
Staging area at the bottom of the valley, far right.

## Wilson Creek Terraced Area



Looking uphill from Terrace #6 toward Terrace #3.  
Terraces excavated, sampled and backfilled.



Compacting soil in terraces

## Wilson Creek Terraced Area



Terrace #1.  
Adding top soil and contouring.



Terraces #4 and #5.  
Contouring.