

# Construction and Stormwater Inspection

August 11, 2017

Operator: BURLINGTON RESOURCES OIL & GAS LP- #26580

Location ID: 439225

Arapahoe County, CO

SESE Section 8 T4S R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Tiberius 4-64 8 /4H  
Location ID: 439225



**Photo 1.** Photo taken north of the topsoil stockpile, facing West. A temporary BMP (filtrexx wattle) has been installed around the entire perimeter of the location.



**Photo 2.** Photo taken from the western location, facing South. A temporary BMP (filtrexx wattle) has been installed around the entire perimeter of the location. Appears there is a vegetative buffer between the western disturbance area and the BMP to aid in stormwater controls.

Inspection Photos  
Location Name: Tiberius 4-64 8 /4H  
Location ID: 439225



**Photo 3.** Photo taken from the entrance of location, facing Southwest. A temporary BMP (filtrexx wattle) has been installed around the entire perimeter of the location. Appears there is a vegetative buffer between the southern disturbance area and the BMP to aid in stormwater controls.



**Photo 4.** Photo taken from the entrance of location, facing North. A temporary BMP (filtrexx wattle) has been installed around the entire perimeter of the location.