

Inspection Photos

8/14/2017

Operator: BARRETT RESOURCES CORP - 6495

Location ID: 407280

Inspection Doc. Number: 675103840

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the former tank battery location, facing northeast. Previous inspection doc. #682502071 required operator to remove risers in accordance to the 2017 Flowline NTO. Risers still remain at the battery location and are now subject to reclamation requirement for removal.