

Inspection Photos

8/14/2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP
- 47120

Location ID: 318950

Inspection Doc. Number: 675103842
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the northeast end of the battery location, facing south. Photo shows meter shed equipment has been removed. Battery and well location waiting additional reclamation work.