

Inspection Photos

8/14/2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP
- 47120

Location ID: 329326

Inspection Doc. Number: 675103845
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID:329326



Photo 1: Photo taken from the south end of the battery location. Photo shows meter shed has been removed, however pipe riser has not been removed. Riser is now subject to reclamation requirements for removal.