

Inspection Photos

8/14/2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP
- 47120

Location ID: 318995

Inspection Doc. Number: 675103845
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120
Location ID: 318995



Photo 1: Photo taken from the well location, facing west. Sundry Doc. #401338816, and schedule doc. #401328993 stated reclamation will be conducted on, or before 7/31/2017. Unable to find any sign that additional reclamation activities have been conducted per the sundry, and schedule, to bring the location back into compliance.



Photo 2: Photo taken from the well location, facing northwest. Sundry Doc. #401338816, and schedule doc. #401328993 stated reclamation will be conducted on, or before 7/31/2017. Unable to find any sign that additional reclamation activities have been conducted per the sundry, and schedule, to bring the location back into compliance.

Inspection Photos
Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120
Location ID: 318995



Photo 3: Photo taken from the well location, facing north. Sundry Doc. #401338816, and schedule doc. #401328993 stated reclamation will be conducted on, or before 7/31/2017. Unable to find any sign that additional reclamation activities have been conducted per the sundry, and schedule, to bring the location back into compliance.



Photo 4: Photo taken from the well location, facing northeast. Sundry Doc. #401338816, and schedule doc. #401328993 stated reclamation will be conducted on, or before 7/31/2017. Unable to find any sign that additional reclamation activities have been conducted per the sundry, and schedule, to bring the location back into compliance.