

# Inspection Photos

8/14/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 405904

Inspection Doc. Number: 675103849

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID:405904



**Photo 1:** Photo taken from the well location, facing west. Photo shows pipe has been removed. Additional reclamation is still required.



**Photo 2:** Photo taken from the east end of the battery location. Photo shows riser equipment remaining on the location.