

Inspection Photos

Location Number: 318760



Photo 1: Unused equipment at wellhead from previous inspection.



Photo 2: Unused equipment has been removed from wellhead area.