

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/09/2017

Submitted Date:

08/10/2017

Document Number:

689400105**FIELD INSPECTION FORM**

Loc ID 334463 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Laramie Energy LLC		cogccnotifications@laramie-energy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295035	WELL	PR	04/24/2013	GW	077-09550	NVEGA 23-324	PR
295036	WELL	PR	03/19/2008	GW	077-09551	NVEGA 23-234	PR
295037	WELL	PR	03/01/2011	GW	077-09552	NVEGA 23-231	PR
295750	WELL	PR	04/29/2008	GW	077-09637	NVEGA 23-144	PR
295751	WELL	PR	04/29/2008	GW	077-09636	NVEGA 26-211	PR
295752	WELL	PR	07/19/2008	GW	077-09635	NVEGA 26-111	PR
295753	WELL	PR	04/29/2008	GW	077-09634	NVEGA 26-311	PR
295754	WELL	PR	04/29/2008	GW	077-09633	NVEGA 23-141	PR
295755	WELL	PR	04/29/2008	GW	077-09632	NVEGA 23-241	PR
295756	WELL	PR	07/23/2013	GW	077-09631	NVEGA 23-341	PR
295757	WELL	PR	04/29/2008	GW	077-09630	NVEGA 23-244	PR
295758	WELL	PR	04/29/2008	GW	077-09629	NVEGA 23-344	PR
295759	WELL	PR	04/29/2008	GW	077-09628	NVEGA 23-331	PR
295760	WELL	PR	06/01/2012	GW	077-09627	NVEGA 23-334	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	400 BBLS	STEEL AST		,

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	400 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>295035</u>	Type:	<u>WELL</u>	API Number:	<u>077-09550</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295036</u>	Type:	<u>WELL</u>	API Number:	<u>077-09551</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295037</u>	Type:	<u>WELL</u>	API Number:	<u>077-09552</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295750</u>	Type:	<u>WELL</u>	API Number:	<u>077-09637</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295751</u>	Type:	<u>WELL</u>	API Number:	<u>077-09636</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295752</u>	Type:	<u>WELL</u>	API Number:	<u>077-09635</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295753</u>	Type:	<u>WELL</u>	API Number:	<u>077-09634</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295754</u>	Type:	<u>WELL</u>	API Number:	<u>077-09633</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295755</u>	Type:	<u>WELL</u>	API Number:	<u>077-09632</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295756</u>	Type:	<u>WELL</u>	API Number:	<u>077-09631</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295757</u>	Type:	<u>WELL</u>	API Number:	<u>077-09630</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295758</u>	Type:	<u>WELL</u>	API Number:	<u>077-09629</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295759</u>	Type:	<u>WELL</u>	API Number:	<u>077-09628</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295760</u>	Type:	<u>WELL</u>	API Number:	<u>077-09627</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Ditches	Pass					
Compaction	Pass	Culverts	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401371831	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4222616">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4222616</a>