

# Inspection Photos

## Location Number: 330153



**Photo 1: Previous inspection**



**Photo 2: Trash (tires) have been removed.**



## Inspection Photos



**Photo 3: Previous inspection,  
compromised berm**



**Photo 4: Berm has been repaired.**





## Inspection Photos



**Photo 5: Previous inspection, weed debris within berm.**



**Photo 6: Weed debris has been removed from within berm.**

