

# Inspection Photos

## Location Number: 450568




Photo 1: Written safety plan in office





Photo 2: Drilling permit in office

# Inspection Photos



**Photo 3: BOP Charts in office**




**Photo 4: Mats and lining under drilling operations.**

# Inspection Photos



**Photo 5: Materials stored under conex**



**Photo 6: Drilling permit on drill floor**