

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401345851

Receive Date:

08/17/2017

Report taken by:

CHRIS CANFIELD

Site Investigation and Remediation Workplan (Initial Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: GREAT WESTERN OPERATING COMPANY LLC	Operator No: 10110	Phone Numbers Phone: (303) 398-0537 Mobile: ()
Address: 1801 BROADWAY #500		
City: DENVER	State: CO Zip: 80202	
Contact Person: Scot Donato	Email: sdonato@gwogco.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 10393

Initial Form 27 Document #: 401345851

PURPOSE INFORMATION

- | | |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other _____ |

SITE INFORMATION

N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: LOCATION	Facility ID: 320251	API #: _____	County Name: ADAMS
Facility Name: GREAT WESTERN ADAMS AGGREGATE 2		Latitude: 39.966849	Longitude: -104.853861
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: SWNE	Sec: 14	Twp: 1S	Range: 67W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications SC

Most Sensitive Adjacent Land Use Rural residential

Is domestic water well within 1/4 mile? Yes

Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

18 water wells - nearest is 175 ft. southwest, Unnamed canal - 530 ft. west, South Platte River - 800 ft. east, Unnamed ponds - 700 ft. southeast and 1,200 ft. southeast, Rural residential subdivision - 375 ft. south

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | |
| <input checked="" type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input checked="" type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
No	GROUNDWATER	None	Limited Subsurface Investigation
No	SOILS	None	Limited Subsurface Investigation

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Between April 4, 2016 and June 14, 2016, Olsson completed a limited subsurface investigation to assess the presence or absence of petroleum hydrocarbon impacts in soil and groundwater, prior to and during the removal of a steel produced water tank (PWT) and two associated culvert vaults. Groundwater samples were collected from three borings located topographically down-gradient from the PWT and culvert vaults. Confirmation soil samples were collected during removal of the PWT and culvert vaults. Approximately 3.6 barrels (0.75 cubic yards) of impacted soil was excavated and disposed of at Buffalo Ridge Landfill.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Continuous soil samples were collected during direct-push boring for characterization and confirmation purposes. Hydrocarbon staining and odors were not observed in soil from any of the seven borings and therefore laboratory analysis of soil samples was not performed. Nine discrete confirmation wall and base soil samples were collected during excavation and removal of the PWT and culvert vaults. Each sample was analyzed for BTEX, TPH, pH, and EC. Confirmation soil sample results were below COGCC Table 910-1 concentration levels for BTEX, TPH, pH, and EC, with the exception of pH reported at 9.08 standard units in one sample.

Proposed Groundwater Sampling

☒ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Seven direct-push borings were advanced to assess groundwater outside of the fenced in tank battery, directly adjacent to the potential source area. The groundwater analytical results show BTEX concentrations were not detected at or above laboratory reporting limits in the samples collected from borings BH-3, BH-4, and BH-5, located directly adjacent to and topographically down-gradient from the PWT and culvert vaults.

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 9

Number of soil samples exceeding 910-1 2

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 0

NA / ND

-- Highest concentration of TPH (mg/kg) 3061

NA Highest concentration of SAR

BTEX > 910-1 No

Vertical Extent > 910-1 (in feet) 0

Groundwater

Number of groundwater samples collected 3

Was extent of groundwater contaminated delineated? Yes

Depth to groundwater (below ground surface, in feet) 9'

Number of groundwater monitoring wells installed 0

Number of groundwater samples exceeding 910-1 0

ND Highest concentration of Benzene (µg/l)

ND Highest concentration of Toluene (µg/l)

ND Highest concentration of Ethylbenzene (µg/l)

ND Highest concentration of Xylene (µg/l)

NA Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

0 Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☒ Were background samples collected as part of this site investigation?

A non-impacted, native soil sample was collected from a wooded area located approximately 150 feet east of the site. The pH value reported was 8.79 standard units.

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☐ Is further site investigation required?

REMEDIAL ACTION PLAN

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Approximately 0.75 cubic yards of impacted soil was excavated from the base of the west culvert vault and disposed of at Buffalo Ridge Landfill. The PWT and culvert vault excavations were backfilled with imported structural fill material on June 17, 2016.

REMEDICATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Approximately 3.6 barrels (0.75 cubic yards) of impacted soil was excavated from the base of the west culvert vault and disposed of at Buffalo Ridge Landfill. The PWT and culvert vault excavations were backfilled with imported structural fill material on June 17, 2016.

Soil Remediation Summary

☐ In Situ

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

☒ Ex Situ

Yes _____ Excavate and offsite disposal
If Yes: Estimated Volume (Cubic Yards) _____ 1
Name of Licensed Disposal Facility or COGCC Facility ID # _____
_____ Excavate and onsite remediation
_____ Land Treatment
_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Other _____

Groundwater Remediation Summary

☐ _____ Bioremediation (or enhanced bioremediation)
☐ _____ Chemical oxidation
☐ _____ Air sparge / Soil vapor extraction
☐ _____ Natural Attenuation
☐ _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater has not been impacted.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: ☐ Quarterly ☐ Semi-Annually ☐ Annually ☒ Other Not applicable.

Report Type: ☐ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report

☐ Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation is not required.

Is the described reclamation complete? _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? _____

If NO, does the seed mix comply with local soil conservation district recommendations? _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, if known. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 04/04/2016

Date of commencement of Site Investigation. _____

Date of completion of Site Investigation. 06/14/2016

REMEDIAL ACTION DATES

Date of commencement of Remediation. 06/13/2016

Date of completion of Remediation. 06/13/2016

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: ` Jason Davidson _____

Title: Senior Geologist _____

Submit Date: ` 08/17/2017 _____

Email: jdavidson@olssonassociates.com _____

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: CHRIS CANFIELD _____

Date: 08/17/2017 _____

Remediation Project Number: 10393 _____

COA Type**Description**

--	--

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

401345851	FORM 27-INITIAL-SUBMITTED
401346023	OTHER

Total Attach: 2 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)