

Construction and Stormwater Inspection

August 11, 2017

Operator: BURLINGTON RESOURCES OIL & GAS LP- #26580

Location ID: 451622

Arapahoe County, CO

NWSW Section 1 T5S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: State Challenger 5-65 2-3 /3BYH

Location ID: 451622



Photo 1. Photo taken from the eastern location, facing West. Topsoil salvage operations IN-PROCESS. Temporary BMP (i.e., filtrex wattle) installed around in the perimeter of the location.



Photo 2. Photo taken from the eastern location, facing North. Photo taken of the topsoil stockpile area.

Inspection Photos

Location Name: State Challenger 5-65 2-3 /3BYH

Location ID: 451622



Photo 3. Photo taken from the southeastern location, facing West. Topsoil salvage operations IN-PROCESS. Temporary BMP (i.e., filtrex wattle) installed around in the perimeter of the location.



Photo 4. Photo taken from the southwestern location, facing West. Topsoil salvage operations IN-PROCESS. Temporary BMP (i.e., filtrex wattle) installed around in the perimeter of the location.