

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/17/2017

Submitted Date:

08/17/2017

Document Number:

689500101

FIELD INSPECTION FORM

Loc ID 316157 Inspector Name: GRANAHAN, KYLE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 49100
Name of Operator: KOCH EXPLORATION COMPANY, LLC
Address: 950 17TH STREET #1900
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Clark, John	505-334-9111	clark23j@kochind.com	Rio Blanco insp

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232253	WELL	PR	03/01/2017	GW	103-09924	WRD UNIT 20-31	SI

General Comment:

Empty text area for general comments.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Present/complete		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 877-352-4660

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#		corrective date
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	1	400 BBLs	HEATED STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 232253 Type: WELL API Number: 103-09924 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI - no leaks/venting

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Gravel	Pass					
Compaction	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT