

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---|-------|------------|
| Type | WELLHEAD | | |
| Comment: | Multiple signs at one well. | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | Date: | 09/18/2017 |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--------------|-------|--|
| Comment: | 800-891-6191 | | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Two out of service tanks in containment. Multiple joints of poly pipe near entrance. | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 11/18/2017 |
| Type | STORAGE OF SUPL | | |
| Comment: | Hoses at tank battery not stored in containment. | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 09/18/2017 |

Overall Good:

Spills:

| Type | Area | Volume | | |
|--|------|--------|--|--|
| In Containment: No | | | | |
| Comment: <input type="text"/> | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

Fencing/:

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 2 | 300 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |

Other (Type) _____

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |

Comment: _____
 Corrective Action: _____ Date: _____

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|------------|---|----------|-----------|---------|--------|
| CONDENSATE | 2 | 300 BBLs | STEEL AST | | |

Comment: [Tanks are labeled OUT OS SERVICE. See housekeeping section of inspection.](#)
 Corrective Action: _____ Date: _____

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | _____ |
| Other (Capacity) | _____ |
| Other (Type) | _____ |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |

Comment: _____
 Corrective Action: _____ Date: _____

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------------|---|----------|-----------|---------|--------|
| PRODUCED WATER | 4 | 400 BBLs | STEEL AST | | |

Comment: _____
 Corrective Action: _____ Date: _____

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | _____ |
| Other (Capacity) | _____ |
| Other (Type) | _____ |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |

Comment: _____
 Corrective Action: _____ Date: _____

Venting:

| | | | |
|--------------------|-------|-------|-------|
| Yes/No | NO | | |
| Comment: | _____ | | |
| Corrective Action: | _____ | Date: | _____ |

Flaring:

| | |
|------|-------|
| Type | _____ |
|------|-------|

| | |
|--------------------|-------|
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 259437 Type: WELL API Number: 077-08730 Status: PR Insp. Status: PR

Facility ID: 262735 Type: WELL API Number: 077-08754 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well was shut in at time of inspection.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Gravel | Pass | | | |
| Compaction | Pass | Compaction | Pass | | | |
| Gravel | Pass | Check Dams | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------|---|
| 689400135 | Buzzard Creek Unit 15 O | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4231715 |