

Inspection Photos

8/17/2017

Operator: PDC ENERGY INC - 69175

Location ID: 323261

Inspection Doc. Number: 675103881

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 323261



Photo 1: Photo taken from the northwest end of the battery location, facing southeast. Photo shows no reclamation work appears to have been conducted at the battery location per CA's from inspection doc. #682502354



Photo 2: Photo taken from the southwest end of the battery location, facing south. Photo shows no reclamation work appears to have been conducted at the access road per CA's from inspection doc. #682502354