

# Inspection Photos

8/17/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 319038

Inspection Doc. Number: 675103883

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the battery location. Photo shows riser has been removed, and additional reclamation work appears to have been conducted.