

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/17/2017

Submitted Date:

08/18/2017

Document Number:

678300885**FIELD INSPECTION FORM**

Loc ID 332847 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436628	TANK BATTERY	AC			-	Camenisch Dos Rios 16-33 Facility	EI
441057	SPILL OR RELEASE	CL	03/04/2015		-	SPILL/RELEASE POINT	EI

General Comment:

tank battery removed per rem project 8313. Spill closed.
No equipment left on site

Inspected Facilities								
Facility ID:	436628	Type:	TANK	API Number: -	Status:	AC	Insp. Status:	EI
Facility ID:	441057	Type:	SPILL OR	API Number: -	Status:	CL	Insp. Status:	EI