

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/11/2017

Submitted Date:

08/14/2017

Document Number:

681902251**FIELD INSPECTION FORM**

Loc ID 434526 Inspector Name: HELGELAND, GARY On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	
Adamczyk, Megan		megan.adamczyk@state.co.u s	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434733	WELL	XX	07/30/2015	LO	123-38301	Pratt 4C-29H-P168	XX

General Comment:

Inspected Facilities

Facility ID: 434733 Type: WELL API Number: 123-38301 Status: XX Insp. Status: XX

Complaint

Comment: On 8/11/2017 COGCC personnel inspected Ensign 153 on the Pratt drilling location. Normal operations were in progress. No noise beyond permitted limits was found. Significant noise was observed however coming from an unrelated "pile driver" located directly north of the Pratt location on top of the Waste Management land fill. The Waste Management pile driver was determined to be the source of the disturbance.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401375785	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226679