

# Construction and Stormwater Inspection

August 17, 2017

Operator: CRESCENT POINT ENERGY U.S. CORP - #10520

Location ID: 447902

Weld County, CO

NENW Section 31 T9N R59W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Shull Pad  
Location ID: 447902



**Photo 1.** Photo taken from the northwestern location, facing Northeast. Topsoil salvage operations IN-PROCESS. Temporary BMP (i.e., ditch) installed around in the entire perimeter of the location.



**Photo 2.** Photo taken from the northwestern location, facing Northeast. Topsoil salvage operations IN-PROCESS.

Inspection Photos  
Location Name: Shull Pad  
Location ID: 447902



**Photo 3.** Photo taken from the southwestern location, facing Southeast. Topsoil salvage operations IN-PROCESS. Temporary BMP (i.e., ditch) installed around in the entire perimeter of the location.



**Photo 4.** Photo taken from the southeastern location, facing Northeast. Topsoil salvage operations IN-PROCESS. Temporary BMP (i.e., ditch) installed around in the entire perimeter of the location. Topsoil stockpile being stored along the southeastern location.