

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/07/2017

Submitted Date:

08/17/2017

Document Number:

674200195

**FIELD INSPECTION FORM**

Loc ID 434526 Inspector Name: Gomez, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 1801 CALIFORNIA STREET #2500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc.inspections@crestonepr.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434525	WELL	DG	11/23/2014	SI	123-38225	Pratt 4G-29H-P168	DG
434527	WELL	DG	07/24/2017	LO	123-38226	Pratt 4D-29H-P168	DG
434528	WELL	DG	07/21/2017	LO	123-38227	Pratt 4F-29H-P168	DG
434529	WELL	DG	07/22/2017	LO	123-38228	Pratt 4E-29H-P168	DG

**General Comment:**

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	#		
Comment:	Drilling mud chiller		
Corrective Action:			Date:
Type: Ancillary equipment	#		
Comment:	Approx 32; sound walls around location		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type	Field Flare		
Comment:	Not in use at time of inspection		
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	<u>434525</u>	Type:	<u>WELL</u>	API Number:	<u>123-38225</u>	Status:	<u>DG</u>	Insp. Status:	<u>DG</u>
Facility ID:	<u>434527</u>	Type:	<u>WELL</u>	API Number:	<u>123-38226</u>	Status:	<u>DG</u>	Insp. Status:	<u>DG</u>
Facility ID:	<u>434528</u>	Type:	<u>WELL</u>	API Number:	<u>123-38227</u>	Status:	<u>DG</u>	Insp. Status:	<u>DG</u>
Facility ID:	<u>434529</u>	Type:	<u>WELL</u>	API Number:	<u>123-38228</u>	Status:	<u>DG</u>	Insp. Status:	<u>DG</u>

Complaint	
Comment:	<p><a href="#">Complaint Received Aug 5, 2017</a></p> <p>Field Inspector Assigned: Jason E. Gomez</p> <p>Complaint Received:</p> <p>Date 8/5/2017 Time 1530 Hrs</p> <p>Complaint Contacted:</p> <p>Date: 8/7/2017 Time</p> <p>Well Number#: Location #: 434526</p> <p>Inspection Document #: 674200195</p> <p>Nature of complaint: Odor</p> <p>Field Inspector Actions:</p> <p>On 8/5/2017, While I was driving with my family in the area of Vista Ridge driving on Hickory drive at approx. 15:30 hrs when I noticed odors in the area which appeared to be coming from the Pratt Drilling location which was located to the NE of Hickory Drive.</p> <p>On 8/7/2017, I went to the Pratt location and contacted the Crestone rig manager I notified him of the odors I had smelled on 8/5/2017 I asked to review drilling records to see if the rig had experienced any abnormal drilling conditions according to drilling records regular drilling was occurring at the time I experienced the odors off location.</p> <p>I advised Crestone to increase odor BMP's to control the odors from leaving location.</p> <p>All information reviewed and site inspection information were submitted to the complaint specialist for further review.</p>
Corrective Action:	Date:

Well Drilling	
<b>Rig:</b>	Rig Name: <u>Ensign 153</u> Pusher/Rig Manager: _____
	Permit Posted: <u>Yes</u> Access Sign: <u>Yes</u>
<b>Well Control Equipment:</b>	
Pipe Ram: <u>YES</u>	Blind Ram: <u>YES</u> Hydril Type: <u>YES</u>
Pressure Test BOP: <u>Pass</u>	Test Pressure PSI: _____ Safety Plan: <u>YES</u>
<b>Drill Fluids Management:</b>	
Lined Pit: _____	Unlined Pit: _____ Closed Loop: <u>YES</u> Semi-Closed Loop: _____
Multi-Well: <u>YES</u>	Disposal Location: <u>Wsate Connection</u>
Comment:	<u>All lighting pointed down and toward the Ground</u>

Corrective Action:		Date:	
--------------------	--	-------	--

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401380054	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4231105">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4231105</a>