

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/17/2017

Submitted Date:

08/18/2017

Document Number:

689400130**FIELD INSPECTION FORM**

Loc ID 334451 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|-------|---------------------------------------|---------------------------------|
| Energy, Laramie | | cogccnotifications@laramie-energy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 290617 | WELL | PR | 05/16/2007 | GW | 077-09288 | NORTH VEGA 27-431 | PR |
| 291424 | WELL | PR | 07/17/2007 | GW | 077-09334 | DELTA 27-321 | PR |
| 291428 | WELL | PR | 07/17/2007 | GW | 077-09335 | DELTA 27-314 | PR |
| 291429 | WELL | PR | 07/17/2007 | GW | 077-09336 | DELTA 27-421 | SI |
| 292063 | WELL | PR | 08/28/2007 | GW | 077-09383 | DELTA 27-334 | PR |
| 292064 | WELL | PR | 08/28/2007 | GW | 077-09382 | DELTA 27-324 | PR |
| 292065 | WELL | PR | 08/28/2007 | GW | 077-09381 | DELTA 27-434 | PR |
| 292066 | WELL | PR | 08/28/2007 | GW | 077-09380 | DELTA 27-424 | PR |

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------------------|-------|--|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 800-891-6191

Corrective Action:

Date:

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 1 | 400 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | |
| Date: | | | | |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------|---|----------|-----------|---------|--------|
| METHANOL | 1 | <50 BBLs | STEEL AST | | , |

| | | |
|--------------------|--|-------|
| Comment: | | |
| Corrective Action: | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| | | | | | |
|--------------------|---|----------|------------------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CONDENSATE | 3 | 400 BBLS | HEATED STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

| | | | | |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>290617</u> | Type: <u>WELL</u> | API Number: <u>077-09288</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>291424</u> | Type: <u>WELL</u> | API Number: <u>077-09334</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>291428</u> | Type: <u>WELL</u> | API Number: <u>077-09335</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>291429</u> | Type: <u>WELL</u> | API Number: <u>077-09336</u> | Status: <u>PR</u> | Insp. Status: <u>SI</u> |

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Well was shut in at time of inspection.

Corrective Action: _____ Date: _____

| | | | | |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>292063</u> | Type: <u>WELL</u> | API Number: <u>077-09383</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>292064</u> | Type: <u>WELL</u> | API Number: <u>077-09382</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>292065</u> | Type: <u>WELL</u> | API Number: <u>077-09381</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>292066</u> | Type: <u>WELL</u> | API Number: <u>077-09380</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches | Pass | Gravel | Pass | | | |
| Compaction | Pass | Compaction | Pass | | | |
| Gravel | Pass | | | | | |
| Berms | Pass | Check Dams | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401380839 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4231718 |