

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/16/2017

Submitted Date:

08/16/2017

Document Number:

689700161**FIELD INSPECTION FORM**

Loc ID 311638	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 20 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
2A Doc Num: _____			

<b>Operator Information:</b> OGCC Operator Number: <u>100185</u> Name of Operator: <u>ENCANA OIL &amp; GAS (USA) INC</u> Address: <u>370 17TH ST STE 1700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>			
---	--	--	--

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282774	WELL	PR	12/01/2009	GW	045-11838	N. PARACHUTE MF07C-4 C04 696	PR
282776	WELL	PR	04/27/2007	GW	045-11836	N.PARACHUTE MF 13D C04 696	PR
282777	WELL	PR	04/12/2007	GW	045-11835	N. PARACHUTE MF04D C04 696	PR
282778	WELL	PR	01/23/2006	GW	045-11834	N.PARACHUTE MF02C C04 696	PR
282779	WELL	PR	01/23/2006	GW	045-11833	N.PARACHUTE MF08C C04 696	PR
282780	WELL	PR	01/23/2006	GW	045-11832	N.PARACHUTE MF03A C04 696	PR
282781	WELL	PR	11/30/2009	GW	045-11831	N. PARACHUTE MF06C-4 C04 696	PR
282784	WELL	PR	01/23/2006	GW	045-11829	N.PARACHUTE MF08A C04 696	PR
282785	WELL	PR	01/23/2006	GW	045-11828	N.PARACHUTE MF01C C04 696	PR
282786	WELL	PR	07/24/2009	GW	045-11827	N. PARACHUTE MF07A-4 C04 696	PR
284640	WELL	PR	12/01/2009	GW	045-12249	N. PARACHUTE MF06B-4 C04 696	PR
295477	WELL	PR	03/01/2010	GW	045-15766	N. PARACHUTE MF01C-4 C04 696	PR
295478	WELL	PR	07/14/2011	GW	045-15767	N. PARACHUTE MF13D-31 C04 69	PR
295479	WELL	PR	02/20/2010	GW	045-15768	N. PARACHUTE MF04B-3 C04 696	PR
295480	WELL	PR	02/15/2010	GW	045-15769	N. PARACHUTE MF03C-4 C04 696	PR
295481	WELL	PR	01/14/2010	GW	045-15770	N. PARACHUTE MF02C-4 C04 696	PR

295482	WELL	PR	02/10/2010	GW	045-15771	N. PARACHUTE MF06A-4 CO4 696	PR
295483	WELL	PR	02/22/2010	GW	045-15772	N. PARACHUTE MF02B-4 CO4 696	PR
295487	WELL	PR	01/13/2010	GW	045-15777	N. PARACHUTE MF13C-31 C04 69	PR

**General Comment:**

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	# 19		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 19		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 19	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	282774	Type:	WELL	API Number:	045-11838	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282776	Type:	WELL	API Number:	045-11836	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282777	Type:	WELL	API Number:	045-11835	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282778	Type:	WELL	API Number:	045-11834	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282779	Type:	WELL	API Number:	045-11833	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282780	Type:	WELL	API Number:	045-11832	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282781	Type:	WELL	API Number:	045-11831	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282784	Type:	WELL	API Number:	045-11829	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	282785	Type:	WELL	API Number:	045-11828	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282786	Type:	WELL	API Number:	045-11827	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284640	Type:	WELL	API Number:	045-12249	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	295477	Type:	WELL	API Number:	045-15766	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	295478	Type:	WELL	API Number:	045-15767	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	295479	Type:	WELL	API Number:	045-15768	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	295480	Type:	WELL	API Number:	045-15769	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	295481	Type:	WELL	API Number:	045-15770	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	295482	Type:	WELL	API Number:	045-15771	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	295483	Type:	WELL	API Number:	045-15772	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	295487	Type:	WELL	API Number:	045-15777	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
				Material Handling And Spill Prevention	Pass	
Seeding	Pass					
		Compaction	Pass			
		Check Dams	Pass			
		Gravel	Pass			
		Culverts	Pass			
Ditches	Pass					
Check Dams	Pass					
Compaction	Pass					
Berms	Pass					
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401378768	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4229589">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4229589</a>
689700162	C 04 Pad	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4229566">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4229566</a>