



Photo 1: View of bermed tank or pit area needs environmental analysis and reclamation.



Photo 2: View of wellhead facing northward.



Photo 3: View of musk thistles (*Carduus nutans*) on the well pad facing northward.



Photo 4: View of spotted knapweed (*Centaurea maculosa*; pink flowering) growing in the well pad.



Photo 5: View of the project area from the southwestern corner facing center. Vegetation is comprised of a mix of weeds and desirable species such as yellow clover (*Melilotus officinalis*), cheatgrass (*Bromus tectorum*), crested wheatgrass (*Agropyron cristatum*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 6: View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 7: View of well sign that is fallen and on the ground.