

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401373741  
Date Received:  
08/11/2017

## FIR RESOLUTION FORM

### CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 74165  
Name of Operator: RENEGADE OIL & GAS COMPANY LLC  
Address: 6155 S MAIN STREET #210  
City: AURORA State: CO Zip: 80016  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
Espinosa, Bill	(303) 829-4982	billespinosa30@yahoo.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 681700581  
Inspection Date: 06/22/2017 FIR Submit Date: 06/23/2017 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: RENEGADE OIL & GAS COMPANY LLC Company Number: 74165  
Address: 6155 S MAIN STREET #210  
City: AURORA State: CO Zip: 80016

### LOCATION - Location ID: 413721

Location Name: PAR STATE 28-14 Number: 2 County: ARAPAHOE  
Qtrqr: SESW Sec: 28 Twp: 5s Range: 64w Meridian: 6  
Latitude: 39.581460 Longitude: -104.559850

### FACILITY - API Number: 05-005-00 Facility ID: 412570

Facility Name: Par State 28-14 Number: #2  
Qtrqr: SESW Sec: 28 Twp: 5s Range: 64w Meridian: 6  
Latitude: 39.581460 Longitude: -104.559850

### CORRECTIVE ACTIONS:

1 ☒ CA# 83270

Corrective Action: Remove and properly dispose of oily waste. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 07/23/2017

Response: CA COMPLETED Date of Completion: 07/21/2017

Operator Comment: CA Complete

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 83271

Corrective Action: Remove and properly dispose of oily waste. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 07/23/2017

Response: CA COMPLETED

Date of Completion: 07/21/2017

Operator  
Comment: CA Complete

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

3 ☒ CA# 83272

Corrective Action: Cap valve to prevent leaks. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 07/23/2017

Response: CA COMPLETED

Date of Completion: 07/21/2017

Operator  
Comment: CA Complete

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA Complete

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Bill Espinosa

Signed: \_\_\_\_\_

Title: Field Supervisor

Date: 8/11/2017 11:46:43 AM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401373741	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files