

**Inspection Photos**  
**Location Name: Dilka 21-6**  
**API: 05-123-23785**




**Photo from prior inspection for comparison**



**Photo 1: Stained soil removed/remediated**

**Inspection Photos**  
**Location Name: Dilka 21-6**  
**API: 05-123-23785**



**Photo from prior inspection for comparison**



**Photo 2: Stained soil removed/remediated**

**Inspection Photos**  
**Location Name: Dilka 21-6**  
**API: 05-123-23785**



**Photo 3: Stained soil in separator house**