

- Sanchez 4 05-067-05321



**Photo 1: 2" riser at R of entrance.**

- Sanchez 4 05-067-05321



**Photo 2: 2" riser at left of entrance.**

- Sanchez 4 05-067-05321



**Photo 3: Line of risers at left of entrance leading to wellhead.**

- Sanchez 4 05-067-05321



**Photo 4: Black poly line coming off hill to back of location.**

- Sanchez 4 05-067-05321



**Photo 5: Production tank with broken nipple and released oil inside containment.**

- Sanchez 4 05-067-05321



**Photo 6: Tank labeled empty.**



- Sanchez 4 05-067-05321



**Photo 7: One of painted rig anchors.**

- Sanchez 4 05-067-05321



**Photo 8: Steel cable pieces on location.**

- Sanchez 4 05-067-05321



Photo 9: Power pole and lines coming to location.

- Sanchez 4 05-067-05321



Photo 10: Signs placed on barrier.