

- Dudley 1 05-067-05766



Photo 1: Painted rig anchor marker.

- Dudley 1 05-067-05766



Photo 2: Debris on location.

- Dudley 1 05-067-05766



Photo 3: Painted risers and valve at SW corner of location.

- Dudley 1 05-067-05766



Photo 4: Painted black poly line and open ended riser.

- Dudley 1 05-067-05766



Photo 5: Wire debris on location.

- Dudley 1 05-067-05766



Photo 6: Above ground lines leaving location.

- Dudley 1 05-067-05766



Photo 7: Location overview.

- Dudley 1 05-067-05766



Photo 8: Stormwater and sediment flow off backside (S) of location.