

# Inspection Photos

8/22/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 329551

Inspection Doc. Number: 675103895

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 329551



**Photo 1:** Photo taken from the battery location, facing south. Photo shows meter shed/equipment associated with the Riter well has not been removed per CA's from Inspection doc. #682502377



**Photo 2:** Photo taken from the north end of the battery location, facing south. Inspection doc. #682502377 required operator to implement stabilization controls.