

Inspection Photos

8/22/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 332748

Inspection Doc. Number: 675103899

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 5: Photo taken from the east end of the battery facility location, facing south. Inspection doc. #682502476 identified four (4) risers at the battery location, and required they be removed in accordance to 1004.a. Photo shows risers have not been removed.