

Inspection Photos

8/22/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 408094

Inspection Doc. Number: 675103907

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the former tank battery location, facing north. Inspection doc. #682502474 required operator to remove riser per 1004.a. Photo shows riser remains on location.