



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Aug 17, 2017 2:43:52 PM MDT
Server Receive Date:	Aug 18, 2017 2:26:42 PM MDT
Reference Number:	20170818-1864929335
Location:	251 Anna Rd, Ignacio, CO 81137, USA Aug 17, 2017 2:42:55 PM MDT [View Map]

Information

Name	reclamationtablet
Date	Aug 17, 2017
Optional - Type Part of the Run Number or Lateral to Filter for Next Question	Lila Cummins A3 and A4
Well Name	CUMMINS, LILA GAS UNIT A 3
API Number	50670960200
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris
Picture North to South	



Picture South to North



Picture East to West



Picture West to East



Completed work description

cut down thistle and reclaimed area cut weeds
around all equipment and pump jacks cleaned up no
spray well