

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/25/2017

Submitted Date:

08/28/2017

Document Number:

666803595**FIELD INSPECTION FORM**

Loc ID 334940 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267970	WELL	PR	02/19/2004	GW	045-09226	HMU 3-15A (I3)	PR
267974	WELL	PR	02/19/2004	GW	045-09229	HMU 3-16 (I3)	PR
267982	WELL	PR	02/19/2004	GW	045-09236	HMU 3-10 (I3)	PR
268005	WELL	PR	02/19/2004	GW	045-09238	HMU 3-15 (I3)	PR
268006	WELL	PR	02/19/2004	GW	045-09239	HMU 3-14A (3)	PR

**General Comment:**Action required on previous inspection have been satisfied

Inspected Facilities				
Facility ID: <u>267970</u>	Type: <u>WELL</u>	API Number: <u>045-09226</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>267974</u>	Type: <u>WELL</u>	API Number: <u>045-09229</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>267982</u>	Type: <u>WELL</u>	API Number: <u>045-09236</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>268005</u>	Type: <u>WELL</u>	API Number: <u>045-09238</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>268006</u>	Type: <u>WELL</u>	API Number: <u>045-09239</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>