

Cover Data

Date: 8/23/17 Inspected By: Ryan Costa

Location/Operator: API# 001-06452 Renegade Oil & Gas

[illegible]

2nd= second hit; P= plant species present but not hit



photo 1: Facing north at the beginning of vegetation transect at the location (Disturbed).



photo 2: Facing south at the end of vegetation transect at the location (Disturbed).



photo 3: Facing southwest at the beginning of vegetation transect off location (reference).



photo 4: Facing northeast at the end of vegetation transect off location (reference).