

Inspection Photos
Location Name: USA Shaw 19
API: 05-081-60020



Photo 1. Some fluid still present in cellar.



Photo 2. No stained soil remaining, flowline clearly marked.