

Inspection Photos
Location Name: Iles Dome Unit 25
API: 05-081-05086



Photo 1. All corrective actions met. No fluid in cellar.