

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/22/2017

Submitted Date:

08/29/2017

Document Number:

689800217

FIELD INSPECTION FORM

Loc ID 312754 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10386
Name of Operator: POC-I LLC
Address: 1888 SHERMAN ST #500
City: DENVER State: CO Zip: 80203

Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|---------------------|---------|
| Tonnsen, John J. | 303-518-3233 | jtonnsen@prellc.com | |
| Choury, Mark J. | 303-818-0341 | mchoury@prellc.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 222176 | WELL | PR | 02/04/2003 | OW | 081-05107 | ILES DOME UNIT 6 | WK |

General Comment:

Inspected Facilities

Facility ID: 222176 Type: WELL API Number: 081-05107 Status: PR Insp. Status: WK

Cement

Cement Contractor

Contractor Name: _____

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 3238

Cement Volume (sx): 120

Good Return During Job: YES

Cement Type: Class G

Comment: Inspector on location to witness plugging. Contractor pumped 120 sxs at the bottom of the wellbore, ~3238. Will wait 4 hours and then tag plug, hoping to be at ~ 2850, if not there, will top off.
No Form 42 for start of plugging received. Inspector notified of operations via phone call.

Corrective Action: _____

Date: _____