

Inspection Photos
Location Name: Schock-Federal 1
API: 05-057-06351



Photo 1. Overview of location taken at the entrance facing northeast.



Photo 2. Stained soil at tank loadout.

Inspection Photos
Location Name: Schock-Federal 1
API: 05-057-06351



Photo 3. Pit.



Photo 4. No wildlife protection on separator exhaust.

Inspection Photos
Location Name: Schock-Federal 1
API: 05-057-06351



Photo 5. 2" steel riser not marked for abandonment or locked out tagged out.