

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/29/2017

Submitted Date:

08/29/2017

Document Number:

689400170

FIELD INSPECTION FORM

Loc ID 323873 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

1 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

Contact Information:

Contact Name	Phone	Email	Comment
Caerus Oil And Gas LLC		COGCC.inspections@caerusoilandgas.com	All Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211054	WELL	PR	03/16/2004	GW	045-06812	TEXACO FEE 6218	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	HEATED STEEL AST		,
Comment:	<input type="text"/>				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities

Facility ID: 211054 Type: WELL API Number: 045-06812 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT