

Inspection Photos
Location Name: Wickstrom #6 CTB
Facility ID # 435380



Photo 1. Sign



Photo 2. Stained soil at production tank leaking load line



Inspection Photos
Location Name: Wickstrom #6CTB
Facility ID # 435380



Pit with oil on surface



Pit

Inspection Photos
Location Name: Wickstrom #6CTB
Facility ID # 435380



Holes in netting



Sign