

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401359779
Date Received:
07/31/2017

FIR RESOLUTION FORM

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 29200
Name of Operator: FAULCONER INC* VERNON E
Address: P O BOX 7995
City: TYLER State: TX Zip: 75711

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Charles, Karen	903-581-4382	kcharles@vefinc.com
Sloan, Buddy	903-581-4382	rsloan@vefinc.com
Wells, Raymond	595-302-7600	rwells@vefinc.com
Labowskie, Steve		steve.labowskie@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 685302850
Inspection Date: 04/27/2017 FIR Submit Date: 05/01/2017 FIR Status:

Inspected Operator Information:

Company Name: FAULCONER INC* VERNON E Company Number: 29200
Address: P O BOX 7995
City: TYLER State: TX Zip: 75711

LOCATION - Location ID: 325149

Location Name: SUNICAL-N33N9W Number: 17SENW County: LA PLATA
Qtrqtr: SENW Sec: 17 Twp: 33N Range: 9W Meridian: N
Latitude: 37.106630 Longitude: -107.853150

FACILITY - API Number: 05-067-00 Facility ID: 214125

Facility Name: SUNICAL Number: 1
Qtrqtr: SENW Sec: 17 Twp: 33N Range: 9W Meridian: N
Latitude: 37.106630 Longitude: -107.853150

CORRECTIVE ACTIONS:

1 CA# 73091

Corrective Action: Install or repair berms or other secondary containment devices per Rule 605.a.(4). Date: 06/01/2017

Response: CA COMPLETED Date of Completion: 06/30/2017

I did not receive a copy of this notice in time to do a Factual Review because several people on the email listed no longer work here and the engineer did not make me aware of the issue.

Operator Comment: the 45 bbls tank where the berm issue is, does not belong to us. It belongs to Williams Midstream. However, we have cleaned up all of our berms. - See attached photos

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 CA# 73092

Corrective Action: Date: 05/17/2017

Response: CA COMPLETED Date of Completion: 06/01/2017

Operator Comment: See attached photos - the deadman by the meter house is marked with a yellow "T" post within a few feet of the deadman, because Williams Midstream personell, back up their trucks right over the top of the deadman when calibrating or other issues with their meter.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

3 CA# 73093

Corrective Action: Date: 05/17/2017

Response: CA COMPLETED Date of Completion: 05/15/2017

Operator Comment: See attached photos

COGCC Decision: Approved pending re-inspection

COGCC Representative:

4 CA# 73094

Corrective Action: Date: 07/01/2017

Response: CA COMPLETED Date of Completion: 07/07/2017

Operator Comment: See attached photos

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The contact information in our system was outdated. Therefore, a few of us that needed to be aware of the Field Inpspection, were not notified in a timely manner. I have been working with the foreman and pumpers in order to get all of the information needed, but it took some time. I have updated the contact information at the beginning of this form so hopefully, in the future, we will not be late in our response times. Thank you.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Karen Charles Signed: _____

Title: Production Analyst Date: 7/31/2017 2:52:36 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401359779	FIR RESOLUTION SUBMITTED
401359901	CA# 73091
401359906	CA# 73091
401359915	CA# 73092
401359918	CA# 73093
401359920	CA# 73094

Total Attach: 6 Files