


**Inspection Photos**  
**Location Name: UPRC Federal 23-1**  
**API: 05-123-19213**



**Wellhead sign on motor shed looking north**



**Stained soil inside of pump jack shed from pump jack motor, west side**

**Inspection Photos**  
**Location Name: UPRC Federal 23-1**  
**API: 05-123-19213**



**Stained soil around pump jack motor, south side**



**Stained soil around pump jack motor, north side**

**Inspection Photos**  
**Location Name: UPRC Federal 23-1**  
**API: 05-123-19213**



**Stained soil in pump jack skid, north side**



**Stained soil north of pump jack**



**Inspection Photos**  
**Location Name: UPRC Federal 23-1**  
**API: 05-123-19213**



**Stained soil around wellhead, looking west**



**Trash inside of heater treater shed, east wall**

**Inspection Photos**  
**Location Name: UPRC Federal 23-1**  
**API: 05-123-19213**



**Trash inside of heater treater shed, north wall**



**5 gallon bucket in heater treater shed, has a hole in it and staining soil**

**Inspection Photos**  
**Location Name: UPRC Federal 23-1**  
**API: 05-123-19213**



**Stained soil in heater treater shed under oil dump**



**2" unused/unmarked steel riser in heater treater shed**

**Inspection Photos**  
**Location Name: UPRC Federal 23-1**  
**API: 05-123-19213**



**2" unused/unmarked steel riser in heater treater shed**



**Stained soil from industrial oil container east side of heater treater shed**

**Inspection Photos**  
**Location Name: UPRC Federal 23-1**  
**API: 05-123-19213**



**Heater treater fire tube gasket is starting to leak**



**1" unused poly riser north side of middle crude tank**

**Inspection Photos**  
**Location Name: UPRC Federal 23-1**  
**API: 05-123-19213**



**1" unused poly riser north side of east crude tank**



**Crude oil tanks looking northeast. Middle tank and east tank need NFPA labels. Middle tank NFPA is not legible, east tank is missing label.**

**Inspection Photos**  
**Location Name: UPRC Federal 23-1**  
**API: 05-123-19213**



**Unused pump jack and equipment on southeast perimeter of location, looking east**



**Unused pump jack and equipment looking south**

**Inspection Photos**  
**Location Name: UPRC Federal 23-1**  
**API: 05-123-19213**



**Unused pump jack equipment looking southwest**



**Battery looking west**