

Form 27A Site Investigation and Remediation Workplan Progress Report

This form shall be used by COGCC to track progress on Remediation Projects.

COGCC Representative: Neidel, Kris
Receive Date: 08/29/2017
Document #: 2495962
Status: APPROVED
Project Number: 7995

Operator Information	Contact Name and Telephone	
Operator Number: 10103	Name: NATHAN KNELL	
Name & Address: SOURCE GAS ENERGY SERVICES COMPANY 600 12TH STREET #300 GOLDEN, 80401	Phone Number: (303)243-3584 Fax Number: () Email:	Facility_id 227607

Location Information:				
Facility ID: 227607				
Facility Name-Number: WOLF CREEK UNIT-GOVT - 5				
QTRQTR: SWNE	SEC: 1	TWP: 9S	RNG: 90W	Meridian: 6

OGCC Employee : **3003693** Tracking Number : **2146336** Project Name : _____
Title : _____ Author : _____ Report Date : _____ Received Date : **09/25/2013** Submitted By : _____
Report Type : **I**
Summary : _____ Date Site Investigation Began : _____ Remediation Start Date : _____ Date Site Investigation Completed : _____
Anticipated Completion Date : _____ Remediation Plan Submitted Date : **09/13/2013** Actual Completion Date : _____

Date (Final Resolution) : _____
Details (Final Resolution) : _____ Check When Case Is Closed : **Y**

doc_num	line_item	detail_type	notify_date	party	contact	details	area_code	phone_num	email
---------	-----------	-------------	-------------	-------	---------	---------	-----------	-----------	-------

Submitted by:	Submitted Title:	Date Submitted:	08/30/2017	Submit Signed:
Approved by: Neidel, Kris	Approved Title: Northwest Environmental P	Approval Date:	08/29/2017	Approval Signed: Yes

Comments/Remarks for this form

COGCC Conditions of Approval

Internal COGCC Comments/Remarks for this form

Based on review of information presented it appears that no further action is necessary at this time and COGCC approves the closure request. However, should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if ground water is found to be significantly impacted, then further investigation and/or remediation activities may be required at the site.

Status: APPROVED