

Location

Lease Road:

	Type Access		
comment:	Trail through farm ground		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 205417 Type: WELL API Number: 009-05101 Status: PR Insp. Status: WK

Workover

Comment: GEMINI WIRELINE, NICHOLS FLUID SERVICE, SARGENT & LILLARD CASING. MIRU SARGENT & LILLARD, PULL TBG FROM WELLBORE. MIRU NICHOLS FLUID SERVICE, FILL CSG W/WATER. MIRU GEMINI WIRELINE, RIH W/GAUGE RING. RIH W/CIBP, SET AT 2965' W/2 SX CMT. CIBP SET AT 2965' DUE TO COUPLING AT 2980'. MIRU NICHOLS FLUID SERVICE, FILL CSG W/WATER. MIRU GEMINI WIRELINE, RIH W/BOND LOG. ESTABLISHED TOC AT 1492'. RIH W/SPLIT SHOT TO CUT CSG. BEGIN CEMENTING AT LATER DATE.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT