

Inspection Photos
Location Name: Jack Berger #4
API: 05-123-08826



Photo from prior inspection for comparison



Photo 1: Stained soil removed, bradenhead plumbed to surface

Inspection Photos
Location Name: Jack Berger #4
API: 05-123-08826



Photo 2: Riser marked