

**Inspection Photos**  
**Location Name: Donald E Miller Et Al B #1**  
**API: 05-123-07493**



**Photo from prior inspection for comparison**



**Photo 1: Tank removed**

## Inspection Photos

Location Name: Donald E Miller Et Al B #1

API: 05-123-07493



Photo 2: Wellhead, looking S



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources