

Inspection Photos
Location Name: Carl A Miller B #10
API: 05-123-08978



Photo 1: Wellhead, looking N. No bradenhead at surface, weeds around wellhead.