

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/31/2017

Submitted Date:

08/31/2017

Document Number:

689700233**FIELD INSPECTION FORM**
 Loc ID 335254 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name          | Phone        | Email                              | Comment |
|-----------------------|--------------|------------------------------------|---------|
| Inspection, Terra TEP | 970-263-2760 | COGCCInspectionReports@terraep.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 210755      | WELL | PR     | 03/20/2017  | GW         | 045-06513 | MOBIL W-8-34  | PR          |
| 271405      | WELL | PR     | 09/28/2004  | GW         | 045-09876 | PA 412-34     | PR          |
| 271408      | WELL | PR     | 09/28/2004  | GW         | 045-09873 | PA 12-34      | PR          |
| 271409      | WELL | PR     | 03/30/2005  | GW         | 045-09872 | PA 512-34     | PR          |
| 271410      | WELL | PR     | 09/28/2004  | GW         | 045-09871 | PA 312-34     | PR          |

**General Comment:**

**Location****Lease Road:**

|                    |        |       |  |
|--------------------|--------|-------|--|
| Type               | Access |       |  |
| comment:           |        |       |  |
| Corrective Action: |        | Date: |  |

Overall Good: ☒**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

**Emergency Contact Number:**

|                    |              |             |
|--------------------|--------------|-------------|
| Comment:           | 970-285-9377 |             |
| Corrective Action: |              | Date: _____ |

Overall Good: ☒**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Fencing/:**

|                    |              |       |  |
|--------------------|--------------|-------|--|
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | SEPARATOR    |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | WELLHEAD     |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |

**Equipment:**

|                       |     |       |                 |
|-----------------------|-----|-------|-----------------|
| Type: Bird Protectors | # 3 |       | corrective date |
| Comment:              |     |       |                 |
| Corrective Action:    |     | Date: |                 |

|                                   |                             |  |       |
|-----------------------------------|-----------------------------|--|-------|
| Type: Plunger Lift                | # 5                         |  |       |
| Comment:                          |                             |  |       |
| Corrective Action:                |                             |  | Date: |
| Type: Ancillary equipment         | # 1                         |  |       |
| Comment:                          | Chemical container at wells |  |       |
| Corrective Action:                |                             |  | Date: |
| Type: Horizontal Heated Separator | # 5                         |  |       |
| Comment:                          |                             |  |       |
| Corrective Action:                |                             |  | Date: |
| Type: Gas Meter Run               | # 1                         |  |       |
| Comment:                          |                             |  |       |
| Corrective Action:                |                             |  | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity  | Type      | Tank ID | SE GPS |
|--------------------|---|-----------|-----------|---------|--------|
| PRODUCED WATER     | 1 | <100 BBLS | STEEL AST |         | ,      |
| Comment:           |   |           |           |         |        |
| Corrective Action: |   |           |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 80 bbl   |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE         | 1 | 300 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type     | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|----------|----------|---------------------|---------------------|-------------|
| Earth    | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment: |          |                     |                     |             |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|--|--|--|--|

**Inspected Facilities**Facility ID: 210755 Type: WELL API Number: 045-06513 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 271405 Type: WELL API Number: 045-09876 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 271408 Type: WELL API Number: 045-09873 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 271409 Type: WELL API Number: 045-09872 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 271410 Type: WELL API Number: 045-09871 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Seeding          | Pass            |                         |                       |               |                          |         |
|                  |                 | Compaction              | Pass                  |               |                          |         |
| Compaction       | Pass            |                         |                       |               |                          |         |
|                  |                 | Culverts                | Pass                  |               |                          |         |
|                  |                 | Gravel                  | Pass                  |               |                          |         |
| Check Dams       | Pass            |                         |                       |               |                          |         |
| Ditches          | Pass            |                         |                       |               |                          |         |
| Gravel           | Pass            |                         |                       |               |                          |         |
|                  |                 | Ditches                 | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description           | URL   |
|--------------|-----------------------|---|
| 689700234    | W 8-24 location photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4241830">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4241830</a> |