

Inspection Photos
Location Name: Thornton 44-5
API: 05-123-23069



Wellhead sign looking south



Wellhead looking south

Inspection Photos
Location Name: Thornton 44-5
API: 05-123-23069



Wellhead looking north



Tank battery looking north

Inspection Photos
Location Name: Thornton 44-5
API: 05-123-23069



Battery looking north from west side of ECD



Erosion southeast corner of separator. Operator was contacted, construction crew in process of installing BMP's